Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

Michael O. Leavitt

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

March 27, 2001

TO:		ž	
THRU:	Daron R. Haddock, Permit Supervisor Gregg A. Galecki, Reclamation Specialist	(A)	
FROM:	Gregg A. Galecki, Reclamation Specialist	+	
RE:	2000 Fourth Quarter Water Monitoring, Canyon Mine, 6000-4		Soldier Canyon
	ta submitted for all of the MRP required sites? tify sites not monitored and reason why, if known:	YES 🔀	NO 🗌
sampled sin	1 6-1 has not been monitored due to blockage within the ce 1997 and the Operator has committed to taking it uring permit renewal.		
See year	t date does the MRP require a five-year resampling requires a five-year resampling requires a five-year resampling requires a five-year resampling requirement and the five-year resampling requirement.	uirements. Con	sider the five-
Resampling	g due date		
	ewal submittal due 10/03/01, renewal due 02/03/02. rameters preceding re-permitting has been found in the		nt to resample for
	I required parameters reported for each site? ments, including identity of monitoring site:	YES 🔀	NO 🗌
	regularities found in the data? ments, including identity of monitoring site:	YES	NO 🛚

5.	5. Were DMR forms submitted for all required sites?						
		1 st month, 2 nd month, 3 rd month,	YES ⊠ YES ⊠ YES ⊠	NO			
6.	Were all required DMR parameters reported Comments, including identity of monitoring		YES 🛚	NO 🗌			
	No Discharge was recorded during the repo	rting period.					
7.	Were irregularities found in the DMR data? Comments, including identity of monitoring	g site:	YES 🗌	NO 🗵			
8. Based on your review, what further actions, if any, do you recommend?							
	No further action is recommended.						
sm O:\	\007018.SOL\FINAL\WQ_00-4.DOC						